



EAA COMPANY LIMITED / Vehicle Roadworthiness Inspection Report

S/No. **TE-2005-146-001**

【Vehicle Details】

Chassis No: **ZZT245-0010121** Model: **UA-ZZT245** Engine Model: **1ZZ**
 Maker: **TOYOTA** 1st Registration Year: **2002/10** Engine No: **1195622**
 Model Name: _____ Manufacture Year: **2002** Weight: **1280** Kg
 Engine Capacity: **1790** cc Type of Vehicle: **Sedan** FF Axis Weight: **770** Kg
 Body Color: **Silver** Mileage(Paper): **67,500** Km FR Axis Weight: _____ Kg
 Fuel Type: **GASOLINE** Odometer: **68,249** km RF Axis Weight: _____ Kg
 RR Axis Weight: **510** Kg

【Inspection Details】

Location: **Yokohama** Inspector: **Hideki Ishii**

【Test Drive】

Abnormal at Acceleration ☒ ☐
 Abnormal at Brake Test ☒ ☐

Pass/Fail

【Exhaust】

CO **0.38** % ☒
 HC **68** ppm ☒
 DS _____ %/m-1 ☒

Pass/Fail

【Headlights】

Luminance R **242** x100cd ☒
 L **359** x100cd ☒

Pass/Fail

Attachment R _____ cm ☒(Height) L _____ cm ☒Optical Axis R _____ cm ☒(Under) L _____ cm ☒Optical Axis R _____ cm ☒(RL) L _____ cm ☒

【Side Slip】

IN / OUT **2.5** mm ☒

Pass/Fail

【Exhaust proximity noise】 ☒
 Average _____ dB(A) ☒

Pass/Fail

【Speedometer】

Difference **-2.3** km/h ☒
 Run-out **0** km/h ☒

Pass/Fail

【Radiation Dose】

Pass/Fail

【Brake System】

FL	247	kg	FR	283	kg	Sum main brake(Weight+55kg)	1335	x0.5=	668	<	Sum Main brake=	908	Pass/Fail
ML		kg	MR		kg	Sum parking brake(Weight+55kg)	1335	x0.2=	267	<	Sum parking brake=	329	<input checked="" type="checkbox"/>
RL	182	kg	RR	196	kg	Sum R wheel brake(axis weight)	510	x0.1=	51	<	Sum R wheel bake=	378	<input checked="" type="checkbox"/>
PL	165	kg	PR	164	kg	Pull:Front(axis Weight+55kg)	825	x0.08=	66	>	Diff b/w R&L axis=	36	<input checked="" type="checkbox"/>
						Pull:Rear(axis Weight)	510	x0.08=	41	>	Diff b/w R&L axis=	14	<input checked="" type="checkbox"/>

【Engine】

Engine ☒ ☐
 Fan belt ☒ ☐
 Battery ☒ ☐
 Master Cylinder ☒ ☐
 Caburetor ☒ ☐
 Fuel Pipes ☒ ☐
 Injection Pump ☒ ☐
 Wiring Haeness ☒ ☐
 Generator ☒ ☐
 Cooling System ☒ ☐
 Manifolds ☒ ☐
 Lubrication System ☒ ☐
 CFC ☒ ☐

Result

【Equipment】

Tool ☒ ☐
 Jack ☒ ☐
 【Underbody】
 Wheel Bearing ☒ ☐
 Springs ☒ ☐
 Shock Absorbers ☒ ☐
 Suspension Fixing ☒ ☐
 Torque Rod ☒ ☐
 Gear Box ☒ ☐
 Steering Rod/Arm ☒ ☐
 Wheel Cylinder ☒ ☐
 Brake Rod/Cable ☒ ☐
 Breake Hose/Pipe ☒ ☐
 Front axle ☒ ☐
 Drive Shaft ☒ ☐
 Propeller Shaft ☒ ☐
 Axle Housing ☒ ☐
 Differential ☒ ☐
 Tyre Size ☒ ☐
 Tyre Condition ☒ ☐
 Tyre ETC ☒ ☐

Result

【Accessory】

A/C ☒ ☐
 Audio ☒ ☐
 Navigation ☒ ☐
 Alloy Wheel ☒ ☐

AT/MT: **AT**

【Interior】

Steering Wheel ☒ ☐
 Power Steering ☒ ☐
 Horn ☒ ☐
 Gauges ☒ ☐
 Climate Control ☒ ☐
 Door ☒ ☐
 Windows ☒ ☐
 Wipers ☒ ☐
 Mirrors(Back & Sides) ☒ ☐
 Shift Lever ☒ ☐
 Safety Belts ☒ ☐
 Brake Pedal ☒ ☐
 Brake Booster ☒ ☐
 Clutch Pedal ☒ ☐
 Clutch Function ☒ ☐

Result

【Lights】

Head lamp ☒ ☐
 Indicator ☒ ☐
 Rear ☒ ☐
 Brake ☒ ☐
 ETC ☒ ☐

Result

【ETC】

Exhaust System ☒ ☐
 Air Suspension ☒ ☐
 Air Brake ☒ ☐
 Fuel Tank ☒ ☐

Result

【Damage】

Exterior ☒ ☐
 Interior ☒ ☐
 Underbody ☒ ☐

Result

F=Repair A=Scratch U=Dent R=Rust CR=Crack D=Damage

【Result】

Inspector Signature **Hideki Ishii**Inspection Date **2020-06-01**

【Reinspection】

Inspector Signature **Hideki Ishii**Inspection Date2 **2020-06-05**

【Fail Parts】

- ①Differential : Not functioning correctly
- ②Battery : Not functioning correctly
- ③R Fender : This is rusted